

Exhibit 2: Site Photos



Above: Tucker Road Ford – stream is flowing across the wet crossing right to left. Sediment accumulating upstream of the ford has raised the elevation of the streambed.

Below: Looking upstream from below the concrete ford.

